

## Multiple load cell errors and Zeroing errors

It has become evident that during manufacturing of the load cells, that the crimping is not perfect, I have noticed many different errors pointing to the load cell and the zeroing of the load cell. 8 out of the last 10 successful service calls regarding these types of errors has been simply to cut off the connection to the load cell and crimp new connectors to the wiring and re-insert in the 4-pin connector.

